


Instruction Of TIF9060E

This instruction is for the user of the Scale.

We hardly recommend that the user of this Scale to get a good acknowledge about all rules and the law.

Shown below is the LCD display.



LCD Indicator	Meaning
lbs, kg, lb oz.	Indicates the unit of the displayed weight.
Battery (twinkle)	Indicates a low battery condition.
The rest of the symbols	Not used for this model.

If the object weight exceeds the scale's weight capacity, it displays "OVER".

Handling:

1. Press ON /OFF (**Red** Button) one time to start the scale (All symbols light then count down to zero).
2. Press one more time to switch off the scale.
3. If necessary, press ZERO (**Green** Button) to obtain a weight reading of zero.
4. Press UNIT (**Yellow** Button) to change the unit (lbs, kg and lb oz cyclically).

General advice:

1. When the Scale is not in and is transported between different working places we recommend to use a case or any other protection against vibrations and other hard environmental conditions.
2. Protect the scale with a transparent plastic bag if there is any risk of leakage or when working in a wet environment.
3. Use only 9VDC battery.