

Bosch Automotive Service Solutions GmbH Lürriper Straße 62 41065 Mönchengladbach Telefon: +49 2161 59906-0 Telefax: +49 2161 59906-16 www.atp-europe.de www.bosch.com

Bosch Automotive Service Solutions GmbH | Lürriper Str. 62 | 41065 Mönchengladbach

To Whom it may Concern

June 2021

We herewith confirm that the leak detector Bosch CS LD 1.0 detects:

CFC, HCFC, HFC, HFO:	R32, R134a, R1234yf, R454A
HC:	R290, R600, R600a
Tracer Gas/Former Gas:	95%N2/5%H2
Ammonia:	NH3

The below Test Results are tested, reported and acknowledged by Intertek, USA

EN 14624:2020 Test Results (as required by Sec 9.1)	R-134A	R-1234yf	R-290
Statische untere Nachweisgrenze / Static lower detection limit / Limite inférieure statique de detection (g/a) ¹	1 g/a	1g/a	0.5 g/a
Dy namische untere Nachweisgrenze / Dy namic lower detection limit / Limite inférieure de détection dy namique (g/a) ¹	1g/a	1g/a	0.5 g/a
Dy namische untere Nachweisgrenze in einer kontarninierten Umgebung/ Dy namic lower detection limit in a contaminated erwiron ment/ Limite inférieure dynamique de détection dans un erwironnement contaminé (g/a) ^a	12 g/a	10 g/a	4 g/a
Reaktionszeit / Response time / Temps de réponse (s) ²	0.5 sec	0.5 sec	0.5 sec
Rückstellungszeit / Zeroing time / Temps de mise à zéro (s)22	-	-	-
Erholungszeit / Recovery time / Temps de recuperation (s) ²	14 sec	10 sec	6 sec

Signed

Rick Pieper General Manager

Bosch Automotive Service Solutions GmbH

Sitz der Gesellschaft: Pollenfeld | Amtsgericht: Ingolstadt HRB 86

Geschäftsführer: Dr. Pio Torre Flores, Carsten Henkel | USt-IdNr: DE 128579454

USt-IdNr. | VAT registration-no. | Nº d'identification TVA: DE128579454 | Steuer-Nr.: 11/290/09930 Finanzamt Bad Segeberg

